

Outlet Parts List

Price	S/N	Maker	Model	Chassis	Status	Parts Name
\$100	762312	Isuzu			New	Clutch cover 8-97109246-0
\$50	762313	Nissan	Mistral	R20	Used	P/W motor & rugulator 80701-2X005
\$30	762314	Subaru	Legacy	BH5	Used	Air flow meter
\$30	762315	Toyota	Prado	RZJ95W	Used	P/W main switch 84820-60180
\$20	762316	Suzuki	Escudo	TX92W	Used	LH brake lamp Koito 33-09509
\$50	762317	Mitsubishi			New	P/W motor MR415408 Aisin 162000-6840 12\
\$20	762318	Toyota			New	Steering rack end 45503-59055
\$10	762319	Isuzu			New	Pilot bearing 9-00090679-0
\$20	762320	Mitsubishi	Airtrek	CU4W	Used	LH fog lamp & indicator lens
\$15	762321	Mitsubishi	C.Grandis	N84W	Used	RH indicator lens R4375R
\$150	762322	Toyota	Celica		New	Brake lamp 08538-20010 x 2
\$100	762323	Mitsubishi	Lancer	CS2A	New	Throttle body
\$1	762324	Toyota			New	Bulb socket 81615-37010
\$50	762325	VW	Golf	E-1HAGG	Used	RH front p/w motor & regulator
\$5	762326	Ford	Spectron	SSF8RF	New	Cotter x 16
\$30	762327	Honda	Ascot	CB3	New	Ignition coil 30510-PT2-006
\$10	762328	Mitsubishi	RVR	N21W	New	P/S belt 5PK-1145
\$10	762329	Mitsubishi	RVR	N23W	New	Alternator belt 4PK985
\$15	762331	Toyota	Chaser	GX105	Used	LH clear lamp Stanley 22-256
\$10	762333	Toyota	Chaser	GX105	Used	Front bumper LH indicator lens Stanley4375L
\$10	762334	Toyota	Chaser	GX105	Used	Front bumper LH indiccaor lens Stanley4375F
\$30	762336	Toyota	Spacio	NZE121N	Used	P/W main switch 84820-13080
\$30	762338	Toyota	Rav4	SXA10	Used	P/W main switch 84820-42040
\$10	762340	Mitsubishi	Pajero io		Used	Ignition coil Diamond FK0150 x 2
\$15	762341	Toyota	Starlet	EP91	Used	LH clear lamp Koito 10-83
\$10	762342	Mitsubishi			New	Water temperature switch MD102329
\$30	762344	Toyota	Cami	GF-J100E	Used	P/W main switch
\$30	762346	Toyota	Vitz		Used	P/W main switch
\$30	762348	Toyota	Harrier		Used	LH & RH brake lamp x 2
\$150	762349	Mercedez	E320	WDB21006	New	LH head lamp
\$20	762350	Nissan	Gloria	Y33	Used	LH brake lamp
\$30	762359	Toyota	Townace	CR31G	Used	RH rear side glass
\$5	762352	Mitsubishi			New	Gasket MR507780 x 3
\$2	762355	Toyota			New	Cylinder head bolt 90910-02150 x 10
\$10	762356	Toyota			New	Hazard switch 84332-28130
\$2	762358	Toyota			New	Camshaft oil seal 90311-35040



SN762312



SN762312-2



SN762313



SN762313-2



SN762314



SN762315



SN762315-2



SN762316



SN762316-2



SN762317



SN762317



SN762317



SN762318



SN762318-2



SN762319



SN762319-2



SN762320-2



SN762320-3



SN762320



SN762320-4



SN762321 SN762321



SN762322



SN762322-2



SN762323



SN762323-2



SN762324



SN762324-2



SN762325 SN762325-2



SN762325-3



SN762326



SN762327



SN762327-2



SN762327



SN762328



SN762329



SN762331



Crack
SN762331



Crack
SN762331



Crack SN762331



SN762333
SN762334



SN762333-2
SN762334-2



SN762336



SN762336-2



SN762338



SN762338-2



SN762340



SN762340-2



SN762341



SN762341-2



SN762342



SN762342-2



SN762344



SN762344-2



SN762346



SN762346-2



SN762346-3



SN762348



SN762348-2



SN762349



SN762349-2



SN762349-3



SN762350



SN762350-2



SN762352



SN762355



SN762356



SN762358



SN762359



SN762359-2

The parts can not be returned nor can be refunded for once ordered & paid for.
Also, we do NOT confirm the parts can be fitted on your vehicle or not
Please, check the parts number & pictures on the list for confirm.

Please, send us an email of your request. we will provide you an invoice after we receive your request
parts@japanesevehicles.com